



Natural Oak - Finished with two coats of wax/oil mix.



Fumed Oak - Traditionally fumed or “smoked”. No dyes or stains are used. Finished with two coats oil/varnish mix.



Ebonised Oak - Traditional iron oxide treatment. No dyes or stains. Finished with two coats of wax/oil mix.



Walnut - Finished with two coats of oil/varnish mix.



White Ash - Finished with three coats of stain and wax/oil mix.